





TO4050-27681860





09848972 · D50401




FIG. 4A




FIG. 4B






FIG. 5

FIG. 6A




*FIG. 6B*



TOPOS "2434360



*FIG. 6c*

104050 2748960





T01050 275849860




FIG. 7C

FIG. 50 "27684860





FIG. 8

FIG. 9



104050 \* 2634860





FIG. 10A

FIG. 10B



104050 2748960

BUILDING  
72

■ WATER FLOW OVER  
OPTIONAL SHIELD

09843972, 0504041






FIG. 10C

**FIG. IIA**




09848972 - 050401


**FIG. IIB**




*FIG. 12A*




*FIG. 12B*



**FIG. 13A**



**FIG. 13B**



**FIG. 13C**

